



## Notes:

- 1. Max speed pot requires the machine to be running with a tachometer on the nip roll to confirm maximum speed setting.
- 2. FACC and RACC need to be set at full counter clockwise (7:00)
- 3. See machine schematic for settings for jumpers J1-J6